

Technical Note

Vertex Troubleshooting CompactLogix PLC

1998-1054 Rev 1 11/23

Vertex HMI may lose the connection with CompactLogix PLC and Vertex HMI gets slowed down due to communication issue with the PLC. Follow the remedy actions referring to the possible scenarios below.

Possible Scenario	Current Behavior/Failure Mode	Remedy Action
New PLC program is loaded to the PLC and the PLC power- cycled while HMI stays on	PLC might be detected by Windows 10 but the link and PLC info in the RSLinx Classic has not been changed, which breaks the connection between PLC and FactoryTalkView. Previous PLC configuration is initialized.	1. Shutdown the RSLinx Classic and wait until RSLinx Classic restarts automatically. RSLinx Classic OEM File Edit View Communications Station DDE/OPC Security Open Project Compact Harmony Exit Exit and Shutdown Shut down the RSLinx Classic Communications Service 2. Edit the Profile depending on the relay option type such as isolated and non-isolated relay Isolated: Relays per card should be 4 Non-isolated: Relays per card should be 16 3. Install the Profile once the communication between PLC and HMI PC is restored.
Computer reboots while PLC stays on	HMI PC does not communicate with PLC	Power-cycle the PLC when the computer is up



Technical Note

Original PLC is removed, and Previous PLC info is left, and Remove the previous PLC information in the new PLC is connected to the USB slot number 15 was Windows registry by following the steps below. computer. (PLC processor assigned to new PLC, which 1. Disconnect USB cable from PLC (PLC should modules were swapped) broke the communication be powered on) between PLC and computer. 2. Press Windows Key + R on Windows machine 3. Type regedit and press Enter key 4. Find Rockwell Automation under HKEY LOCAL MACHINE\SOFTWARE 5. Delete the Rockwell Automation and close the Registry Editor Registry Editor File Edit View Favorites Help Computer\HKEY_LOCAL_MACHINE\SOFTWARE\Rockwell Automation ab (Default) Policies PSAppDeployToolkit Realtek RegisteredApplicatio VbpSlotLru Rockwell Software Scooter Software 6. Reconnect USB cable to PLC 7. Check the connection between PLC and computer Incorrect PLC profile was PLC reports a major fault on Install a Profile with correct PLC configurations installed with incorrect Relays PLC status display and power cycle the PLC per card and number of PLC Isolated: Relays per card should be 4 **Relay Cards** Non-isolated: Relays per card should be 16 Configure PLC: PLC Definition Turn the Mode switch on the PLC from RUN to Configure PLC | Set Alarm Relays | Set Fault Relays | REM and REM to PROG and back to RUN PLC Configuration PLC Relay Cards (0 - 22) Relay PLC's ▼ Relays per Card 14 Fault Relay Count (2 · 16)



Technical Note

Find out more: www.honeywellanalytics.com

www.raesystems.com

Contact Honeywell Analytics:

Europe, Middle East, Africa

Life Safety Distribution GmbH
Javastrasse 2
8604 Hegnau
Switzerland
Tel: +41 (0)44 943 4300
Fax: +41 (0)44 943 4398
gasdetection@honeywell.com
Customer Service:

Tel: 00800 333 222 44 (Freephone number)
Tel: +41 44 943 4380 (Alternative number)
Fax: 00800 333 222 55
Middle East Tel: +971 4 450 5800 (Fixed Gas Detection)
Middle East Tel: +971 4 450 5852 (Portable Gas Detection)

Americas

Honeywell Analytics Distribution Inc. 405 Barclay Blvd. Lincolnshire, IL 60069 USA

Tel: +1 847 955 8200 Toll free: +1 800 538 0363 Fax: +1 847 955 8210 detectgas@honeywell.com

RAE Systems by Honeywell Phone: 408.952.8200 Toll Free: 1.888.723.4800 Fax: 408.952.8480

Asia Pacific

Honeywell Industrial Safety
7F SangAm IT Tower,
434, Worldcupbuk-ro, Mapo-gu,
Seoul 03922,
Korea
Tel: +82 (0) 2 6909 0300
Fax: +82 (0) 2 2025 0328
India Tel: +91 124 4752700
China Tel: +86 10 5885 8788 3000
analytics.ap@honeywell.com
Technical Services
EMEA: HAexpert@honeywell.com
US: ha.us.service@honeywell.com

Technical Services ha.us.service@honeywell.com

AP: ha.ap.service@honeywell.com