Gamewell FCI FIRE CONTROL INSTRUMENTS by Honeywell

Technical Bulletin

No. T16.2

March 2016

IMPORTANT: LCD-SLP Backlight Shutoff

Gamewell-FCI has discovered an issue regarding the backlight of the LCD-SLP failing to shut off when the E3 or S3 series Fire Alarm Control Panel is operating on back-up battery power only. During this event, the LCD-SLP will draw a higher amount of current than designed.

To resolve this issue, the **Trouble Acknowledge** key must be pressed after the system goes onto backup battery power (as show in Figure 1 below). Once the Trouble Acknowledge key has been pressed, the LCD-SLP backlight will shut off, and current draw levels will be as intended.



Figure 1. LCD-SLP Trouble Acknowledge

Gamewell-FCI recommends that customers using the LCD-SLP upgrade to the latest firmware release to resolve this issue.

Gamewell-FCI strongly recommends upgrading to the latest version of CAMWorks **prior** to upgrading the LCD-SLP.

Note: *Upgrading the LCD-SLP from v1.02 (or earlier) using CAMWorks v3.32.002 (or earlier), requires first upgrading the LCD-SLP to v2.00.070 then to v2.10.028.*

For additional questions or support on system compatibility, please contact Gamewell-FCI Technical Support at 1-800-274-4324 or Gamewell-FCI.Tech@honeywell.com.

Sincerely,

Chuck Han
Product Marketing
Honeywell Security and Fire
Gamewell-FCI by Honeywell