GENT
by Honeywell

Technical Bulletin	TB 10019

To: System Integrators, Gent Services	Date: 10/12/2003
	Status: Active
	Type: Gent/SI

Product – Part affected:
3400 & BS Vigilon, Local controller V3.71

Details:
The way default message routing is stored on this version of card has changed.
Basic massage routing used to be part of the software; this has been removed and added in as default set up in the configurable message routing. This has been done to allow more configurability of message routing
This may course problems when upgrading panels. As the configuration will be over written, when the site specific configuration is uploaded.
Previously NW cards out putted all information, this now needs linking to required MG

Action:
On new jobs there will be no noticeable difference.

On upgraded panels ensure that message routing is fully set up and working.

Default message routing (all panels get all messages)
Messages 0-15, output, all,
Messages 0-15, link 1,

Global, reset, both, 1
Global, silence, both, 1
Global, sound, both, 1

Assign, group 0-128, Mgroup 1

If a panel is required to output information only, then messages for the network card need linking to the relevant Master group

If printer and repeat panels are required to display / print network information then card 15 for the printer or the loop card number the repeat is on need linking to the relevant master group.

Name: Peter Dodge