GENT
by Honeywell

Technical Bulletin	TB 10034

To: System Integrators, Novar Gent Services	Date: 02/08/2004
	Status: Active
	Type: Gent/SI

Product – Part affected: S-cubed sounders, intermittent activation with incremented volume.
Details: When using the increment volume feature, the sounder seems to start at full volume for a short period of time and then drop down to the start volume before incrementing back up.
Action: The S-cubed increment option does not work with pulsed input signals (class change). The charge held in the sounder prevents this from working. Do not use the increment volume option when working with pulsed input signal. This does not affect pulsed signals created by the panels FABs and SABs (signal 1).

Name: Peter Dodge