GENT
by Honeywell

Technical Bulletin	TB 10042

To: System Integrators, Novar Gent Services	Date: 25/11/2004
	Status: Active
	Type: Gent/SI

Product – Part affected:
Retro S-cubed sounders, not sounding

Details:
A problem has been highlighted with retro S-cubed sounders not sounding.
This is only a problem if the sounder is inserted on the comm. Tool, this is because the default volume is set to 0 by the comm. Tool.
If the sounder is added to the loop and then the config downloaded there is no problem.

Action:
If you find this problem then please ensure that the volume setting on the device config. page of the comm. tool is set to 100% this is shown just above sectors 11 and 12.
The default volume has been changed to 100% and will be released in the next version of the comm. tool

Name: Peter Dodge