GENT
by Honeywell

Technical Bulletin	TB 10103

To: Gent by Honeywell, System Integrators & SMS	Date: 28/11/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Loss of site specific sounder patterns, LPC 3.92 / 4.32

Details:
An issue has been highlighted after sounder patterns have been altered from there defaults.
When an individual loop is reset the sound patterns for that loop are not recovered from the MCC and it defaults back to our normal defaults.
Resetting of the MCC (card 0) will restore the site sounder patterns as required.
This problem also occurs when the panel is rebooted; the sounder patterns are not recovered back to the loop cards.
Resetting card 0 would again restore the correct patterns.

Action:
Please ensure all engineers are aware of this issue.
The problem has been fixed in the next release of software, which is due for release in January 2006.

Name: Peter Dodge