GENT
by Honeywell

Technical Bulletin	TB 10145

To: Gent by Honeywell & System Integrators.	Date:29/09/2009
	Status: Active
	Type: SI

Product:
Vigilon, MCC v3.96/4.41, 4.42 and 3400/34000 detector, states not working

Details:
When using 3400/34000 detectors and MCC software versions 3.96 / 4.41, 4.42 the following states do not work correctly.

State 5 optical only
State 12, 13 &14 heat only

These will work as a default detector, state 0
This may result in an increase in unwanted alarms.

Action:
Ensure all engineers are aware of this issue.

Review the config of any jobs done with the above software and devices to see if any of these states have been used.

Sites using MCC v3.96 / 4.41, 4.42 and 3400/34000 detectors set to these states should backdate there software to V3.94 / 4.38 Please contact Martin Phillips 0116 2462158 to obtain this software. Until a new release of software is available.

Name: Peter Dodge