GENT
by Honeywell

Technical Bulletin	TB 10155

To: Gent by Honeywell, System Integrators	Date: 7/05/10
	Status: Active
	Type: SI

Product – Part affected:
Issue found with comm. tool v1.26

Details:
The following issues have been found with commissioning tool v1.26.

1. Deleting a sounder from the configuration comes back with improper argument
2. When setting up sector linking, if you go back and check the trigger sector has reduced by one.
3. Repeat panel default setup was for no message passing.
4. Adding a devices to a configuration comes back with "multiple rows updated"
5. Inserting a device directly before an S3 devices, all subsequent S3 devices in the S3 config page devices numbers are not incremented.

Action:
These will all be fixed on comm. tool 1.27

1. S3 database was corrupted taking a new retrieval should resolve this. In the next comm. tool the database will be checked and fixed if this occurs
2. Duplicate rows have been entered in the sector linking page, a new retrieval should resolve this. in the next comm. tool the database will be checked and fixed if this occurs
3. This will be changed so all fire and fault events seen by that panel will also be seen by the repeat as default.
4. Duplicate rows have been entered; a new retrieval should resolve this. In the next comm. tool the database will be checked and fixed if this occurs
5. Work around; insert device two devices before any S3 devices. Then change the devices type on the devices preceding the S3 devices. S3 table not being updated correctly, fixed in next release.

Name: Peter Dodge