GENT
by Honeywell

Technical Bulletin

TB:10202 I March 2015

Product parts affected

Commissioning Tool v1.29 Services Pack 1. Adding interface affecting sectoring.



Details

When using Comm. Tool v1.29 Services Pack 1 (sp1) on unsafe loops.

If you insert a mains powered or sectorable interfaces, the channel sectoring for any subsequent Sectorable / Mains Interfaces on that loop will be incorrect or removed completely.

Action

We recommend that you review any sites that have had mains / sectorable interfaces added using 1.29 or 1.29sp1 and ensure that the channels are in the desired sectors.

Jobs where you are required to insert mains or sectorable interfaces make a note of any existing sectorable interface channel sectoring. Add the new devices and then confirm channel sectoring is correct for these devices.

This issue is fixed in Comm. Tool v1.30 which will be out shortly

If you have any questions please contact Gent Technical Services on 0116 246 2134.

Technical Support
140 Waterside Road
Hamilton Industrial Park
Leicester
LE5 1TN

t 0116 2462134
e technical.services@honeywell.com
w www.gentexpert.co.uk