

## PRODUCT NOTICE


### Version Release Known Issues

**Product Name:** IntelliDoX  
**Version:** 12.200  
**Release Date:** October 10th, 2021

## KNOWN ISSUES AND WORKAROUNDS

Dear Colleagues and Customers,

Due to the need to increase the flow rate for NH<sub>3</sub>, CL<sub>2</sub>, NO<sub>2</sub>, and HCL to allow calibration and bump testing in all 5 bays on the IntelliDoX for BW Solo, the new firmware version (12.200) was released. This firmware version was also released to support Safety Suite Device Configurator (SSDC) with additional features for BW Icon and BW Flex.

Warning Message	Description	Solution
	This error appears because the configuration was modified. A new configuration parameter for the new sensors was added and this warning is shown.	In order to make the message disappear press the  to remove the message from the screen.
	This message may appear only while the IntelliDoX is in a gang arrangement. If one IntelliDoX in this arrangement displays the warning message "CONFIGURATION CORRUPT SETTINGS LOADED FROM FILE", it is likely that another IntelliDoX will show the "MULTI-DOCK COMMUNICATION FAILURE" warning message since the devices have different configuration parameters.	In order to make the message disappear press the  to remove the message from the screen.

The acknowledgement of these warning messages will not have a negative impact in the performance of the product.