Honeywell

NOTIFIER®

12 Clintonville Road
Northford, CT 06472-1653 USA

203-484-7161
203-484-7118 Fax

February 6, 2014

Re: Reissue of System Sensor Safety Bulletin concerning the BEAM1224S, BEAM1224SA

In June of 2013 NOTIFIER communicated an issue regarding the System Sensor BEAM1224S and BEAM1224SA beam detectors manufactured between the first week of November 2012 and third week of May 2013; date codes 2111 – 3053.

NOTIFIER is now working with System Sensor to reissue the bulletin to insure that the recommended corrective actions have been taken. Please review the accompanying System Sensor Safety Bulletin for specific details on the aforementioned issue and the recommended corrective actions.

Please contact your NOTIFIER Customer Service Representative to obtain an RMA for return of any affected beam detectors purchased from NOTIFIER.

Please contact System Sensor Technical Support at 1-800-SENSOR2 if you have any technical questions pertaining to this notice.

Sincerely,

Daniel Corbett
Product Manager, NOTIFIER

Communication of CPSC action in connection with the Safety Bulletin issued May of 2013

Summary of issue: BEAM1224S operation after a low power condition
Level of urgency: High – Urgent Attention Required
Model number: BEAM1224S

In May of 2013, we released a Safety Bulletin regarding a potential risk when using the BEAM1224S Reflected Beam Smoke Detector with certain power supplies. Our records indicate that you purchased units for resale that fall within the affected date range. In May, we asked you to communicate that bulletin to your customers. A copy of the bulletin can be found on the System Sensor website at:

http://www.systemsensor.com/pdf/bulletins/BEAM1224S-Safety-bulletin.pdf

or by calling 1-800-SENSOR2 and asking for information regarding the Beam Detector Safety Bulletin.

System Sensor is working with the Consumer Product Safety Commission (CPSC) to communicate this bulletin on the CPSC website:

http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/System-Sensor-Recalls-Reflected-Beam-Smoke-Detectors/

This CPSC bulletin correlates to the original Safety Bulletin published in May of 2013. It is not an indication of a new or broader issue.

This release by the CPSC may lead to new inquiries, and we are requesting your support. Please **ensure that your customers have checked and rectified any installations that do not meet the recommendations contained within the May bulletin.**

If you require support from System Sensor to execute replacement of any units or resolve any installation questions, we urge you to please contact our Technical Support team at 1-800-SENSOR2. Let the support agent know that you are calling regarding the Beam Detector Safety Bulletin.