NOTIFIER® by Honeywell

Safety Bulletin

February 19, 2013

Re: System Sensor Safety Bulletin


NOTIFIER has been informed of an issue with the System Sensor 2151 series, i3 series, CO1224 series and D2 detectors manufactured the 4th and 5th weeks of January 2013; date codes 3014 and 3015.

Please review the accompanying System Sensor Safety Bulletin for specific details on the aforementioned issue and the recommended corrective actions.

Please contact your NOTIFIER Customer Service Representative to obtain an RMA for return of any affected detectors purchased from NOTIFIER.

Please contact System Sensor Technical Support at 1-800-SENSOR2 if you have any technical questions pertaining to this notice.

Sincerely,



Daniel Corbett
Product Manager, NOTIFIER