Gamewell
A 150-Year Tradition
by Honeywell

Technical Bulletin

To: Gamewell Engineered Systems Distributors

Date: 8/30/2005

Re: 5601P Mechanical Heat Detector to Replace 5601

The 5601 mechanical heat detector, manufactured by System Sensor, will be discontinued and replaced with the 5601P. The 5601P is the same as the 5601, Single Circuit 135° F fixed-temp/rate-of-rise, with the exception that the detector housing has no exterior letters, numbers or markings. The 5601P is UL, FM, CSFM and MEA listed.

The 5601 will be discontinued September 30, 2005. Thereafter, only orders for the 5601P will be accepted.

We appreciate your cooperation during this transition period. In the meantime, should you have any questions regarding this announcement, please feel free to contact your Gamewell Customer Service Representative at 203-484-7161.

This Technical Bulletin is generated to alert all personnel of important application, operational and installation information. Please route this information to all office and field personnel.

Gamewell
12 Clintonville Road • Northford, CT 06472 • USA
Phone: 203-484-7161 • Fax: 203-484-7118