GENT
by Honeywell

Technical Bulletin	TB 10046

To: System Integrators, Novar Gent Services	Date: 31/01/2005
	Status: Active
	Type: Gent/SI

Product – Part affected:
BS and EN54 repeat panels not showing long labels
Details:
A problem has been found with repeat panels on both BS and EN54 where the repeat panel does not show long labels and replaces them with random characters. This only occurs with repeat panel software version 3.72 for BS and version 4.13 for EN.
Action:
This has been fixed in repeat software version 3.73 for BS and 4.14 for EN. Please upgrade repeat panel where necessary

Name: Peter Dodge