GENT
by Honeywell

Technical Bulletin	TB 10070

To: System Integrators, Novar Gent Services	Date: 21/10/2005
	Status: Active
	Type: Gent/SI

Product – Part affected:
Release of new MCC V3.92

Details:
A problem with the BS MCC V3.90-3.91 has been found where interface I/O line used at triggers for command builds were not operating correctly.
Any command build being actioned by an I/O line will not operate.
If this problem existed on site it should have be picked up at commissioning as this would never have worked.

Action:
Any site with BS MCC cards, which are using interface I/O lines as triggers for command builds should be upgraded to V3.92

Name: Peter Dodge