GENT
by Honeywell

Technical Bulletin	TB 10082

To: Gent by Honeywell, System Integrators & SMS	Date: 7/3/2006
	Status: Active
	Type: SI / SMS

Product – Part affected:
Device labels being lost with loop cards V3.92 and V4.32

Details:
We are investigating a problem that when a loop card is reset or the system reboots after a loop has changed since the last back up the devices labels will be lost.

Action:
If this occurs carrying out a recovery will re-instate the devices labels. Using allocate instead of reset does not seem to cause this issue.
We are continuing to investigate. Please look out for future technical bulletins concerning this matter.

Name: Peter Dodge