GENT
by Honeywell

Technical Bulletin	TB 10088

To: Gent by Honeywell, System Integrators & SMS	Date: 21/6/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Vigilon loop cards, pointer corrupt
Details:
We have had a few people ringing in with the following error messages “pointer missing at card X” or “pointer corrupt at card X”
Action:
If you see this problem, please power down the panel for at least 3 minutes. If the fault persists please contact technical support.

Name: Peter Dodge