GENT
by Honeywell

Technical Bulletin	TB 10153

To: Gent by Honeywell, System Integrators	Date: 16/04/10
	Status: Active
	Type: SI

Product – Part affected:
MCC v4.41 & LPC v4.39. Disabling detection and sounder

Details:

It has been noticed that with panel software MCC v4.41 & LPC v4.39. If you disable the sensor and then sounder. A short while later the sensor disablement disappears from the disablement list.
The sensor and sounder are still however both disabled. If you re enable the sounder the sensor disablement then comes back in.

Action:
The above issue has been fixed in LPC 4.41

Please make sure all engineers are aware of this issue.

Name: Peter Dodge