NOTIFIER by Honeywell

Technical Bulletin

Reference #: 18-006
Date: 13th June 2018

ONYX Works Workstation Firmware up-grade Version 4.23

NOTIFIER has identified a non-safety related issue with Version 4.22 ONYX Works Firmware which can cause PC-gateways to lose communication with the client after 7 days from commissioning.

To correct this issue, we recommend for any ONYX Works workstations running version 4.22 to be upgraded to version 4.23 at the next service interval.

The latest firmware is available from NOTIFIER.

Please contact your NOTIFIER product support for any technical questions.