NOTIFIER® by Honeywell

Technical Bulletin

Reference #: 18-010
Date: 7th December 2018

Release ONYXWorks® and FirstVision™ Firmware - Version 4.30

NOTIFIER® is pleased to announce the release of ONYXWorks and FirstVision firmware version 4.30. With the advent of Version 4, ONYXWorks and FirstVision were platformed, therefore, please note for site installations: ONYXWorks® workstations and/or FirstVision™ units on a NOTI•FIRE•NET™ must operate on the same software version. All gateways on the NOTI-FIRE-NET must also operate on the same software version as the OW and FirstVision.



Changes and new features:

- PC Monitor merged with OW software
- Configuration Tool – Redesigned, User-Friendly Display
- 'Point Alias' field has been restored for output
- Test Monitoring Mode - Test Monitoring Mode allows test events to be managed in a separate window on the workstation, eliminating nuisance alarms in the main workstation display.
- Default Logout Monitoring Profiles
- Look Ahead - Look Ahead feature prevents false alarms by warning users if a disabled device is in an active state of alarm.

Corrected issue:

- in Configuration Tool
    - where Auto-Place did not operate correctly when duplicate node addresses are present.
    - Related to curved walls in .DXF files.
- where system performance slowed down after importing large .DXF files.
- in NOTIFY-IP where multiple gateways could not be paged simultaneously.
- of a malfunction of WebPortal Gateway, when commas in customer or building name(s) are included
- where system didn't display alarms properly in 'Show Only OFF Normals' setting.
- related to 'Automatically Print Floorplans' feature, when printing floor plans on receipt of multiple alarms.
- related to Monitoring Profile Change.
- related to Navigation Icons where nav icons displayed alarm incorrectly.
- related to New Screen, where a navigation error occurred when a New Screen was created under the Home Screen
- related to Floorplan printing scaling, where it did not match paper size.
- related to Point navigation from lists, where at a double click on "New event" or on "acknowledged event", auto navigation did not screen all lists in the same way.
- related to Export Database Errors, where Export Database to All workstations via PC monitor did abort mid progress.

Please note: Version 4.30 does not support HS-GW-EMPCA gateway hardware. Versions 4.23 were the final software versions to support HS-GW-EMPCA hardware.

ONYXWorks® and FirstVision™ Version 4.30 are available to order now.

Resources & Support:

Please contact your Notifier Systems Consultant to discuss specific replacement applications or support questions.

Technical questions should be directed to Notifier technical support. **Tel: 1800 220 345 (Toll Free)**