NOTIFIER®

12 Clintonville Road
Northford, CT 06472-1653 USA

203-484-7161
203-484-7118 Fax

TECHNICAL BULLETIN

November 8, 2004


Document TB04-11-01


System Sensor recently discovered that a remote test failure may occur with the addressable FAPT-851 Acclimate Plus™ detector. When a NOTIFIER addressable control panel initiates a periodic remote test, the FAPT-851's calibration may cause the detector to fail the test. In these cases, the fire alarm control panel will indicate a trouble condition and display a message indicating that the smoke detector has failed the test. Detectors which fail to test properly should be replaced immediately with new units which have been corrected by System Sensor.

This issue may affect units manufactured between July 6th, 2004 (date code 4071) and September 29th, 2004 (date code 4095).

The date code can be found on the unit's product ID label or on the carton label. If you have any new, unused inventory within this date range, please contact your NOTIFIER Customer Service Representative to arrange its return and receive credit. To replace an installed FAPT-851 exhibiting the conditions described in this Technical Bulletin, please contact your NOTIFIER Customer Service Representative to arrange for a warranty replacement. Please order new detectors per your normal ordering procedure. FAPT-851's that are removed should be returned via our standard RMA process to receive credit and a $5 labor reimbursement.

Product Label





Carton Label

If you have any questions regarding this product issue, please contact your Notifier Customer Service Representative at (203)484-7161. We appreciate your cooperation and understanding, and apologize for any inconvenience resulting from this issue.