NOTIFIER®

12 Clintonville Road
Northford, CT 06472-1653 USA

203-484-7161
203-484-7118 Fax

TECHNICAL BULLETIN

5601 Mechanical Heat Detector to be replaced with 5601P

August 25, 2005

Document TB05-08-03

The 5601 mechanical heat detector, manufactured by System Sensor, will be discontinued and replaced with the 5601P. The 5601P is the same as the 5601, Single Circuit 135° F fixed-temp/rate-of-rise, with the exception that the detector housing has no exterior markings. The 5601P is UL, FM, CSFM and MEA listed.

The 5601 will be discontinued September 30, 2005. Thereafter, only orders for the 5601P will be accepted.

We appreciate your cooperation during this transition period. In the mean time, should you have any questions regarding this announcement, please feel free to contact your NOTIFIER Customer Service Representative at (203) 484-7161.