GENT
by Honeywell

Technical Bulletin	TB 10024

To: System Integrators, Novar Gent Services	Date: 03/03/2004
	Status: Inactive
	Type: Gent/SI

Product – Part affected: Vigilon Zonal display, rebooting
Details: A problem has been noted with the Vigilon zonal display where it continually re-boots. This occurs when there are more than 5 cards in the panel. The problem seems to be load related and if there are less than 5 cards there is not a problem with panel operation This is currently being investigated
Action: This is for your information; please look out for further announcements on this issue.

Name: Peter Dodge