GENT
by Honeywell

Technical Bulletin	TB 10029

To: System Integrators, Novar Gent Services	Date: 25/05/2004
	Status: Supercedes TB 10028
	Type: Gent/SI

Product – Part affected: Vigilon / 3400 Commissioning tool V1.16, ref TB 10028
Details: A possible problem with sector linking information not being sent back to the panel. As highlighted in TB10028
Action: The commissioning tool does send sector linking information back to the panel as long as the correct Domain and Node numbers are selected on the download. Look at the card status for card 0, this gives the Domain and Node details for that panel. Ensure the domain and node details on the commissioning tool are set-up with the same values as were found on the panel.

Name: Peter Dodge