GENT
by Honeywell

Technical Bulletin	TB 10040

To: System Integrators, Novar Gent Services	Date: 05/10/2004
	Status: Active
	Type: Gent/SI

Product – Part affected:
New I/O card V4.07 talking with supervisor

Details:
A problem has been found with the new I/O cards V4.07 when connected to a supervisor PC. Not all panel details from across the network are pulled back to supervisor.

Action:
This problem has been resolved and released in V4.08 of the I/O card.

If you have an I/O card with V4.07 software that you are going to use with supervisor then please contact Technical support who will send out a new chip.

Name: Peter Dodge