GENT
by Honeywell

Technical Bulletin	TB 10056

To: System Integrators, Novar Gent Services	Date: 09/05/2005
	Status: Active
	Type: Gent/SI

Product – Part affected:
Vigilon, 3400 & Compact. “Backup required at card X” and "25600 is undefined 128 at card X"

Details:
The following two messages are being seen on resent releases of LPC cards “Backup required at card X” and "25600 is undefined 128 at card X"
Backup required should only appear after a change has been made to the panel config, however this is also being seen after I/O channels have been disabled.
Neither of these effect the operation of the fire alarm system.

Action:
Both of these issue have been fixed and released in BS V3.90 and EN V4.31.

Name: Peter Dodge