GENT
by Honeywell

Technical Bulletin	TB 10071

To: System Integrators, Novar Gent Services	Date: 21/10/2005
	Status: Active
	Type: Gent/SI

Product – Part affected:
Uploading changes with commissioning tool V1.20 and MCC / LPC V3.92 &V4.32

Details:
The way that the commissioning tool and panel operate when data is sent to them have changed when you use both comm. tool V1.20 along with MCC and LPC software V3.92 or V4.32 and above.
When the above software's are used you will find the upload time from the comm. tool is much quicker. Information for the S3 & S4 is now passed to the panel which then loads it onto each of these devices.
The changes in both the comm. tool and panel software operation is intended to eliminate memory corrupt problems during commissioning.

Please note that with this new software after the comm. tool has finished information is still being sent to the devices. So you may have to wait for 1- 2 minutes before your new configuration takes effect. You will also find that if you try to back up cards during this time you will get a message "error backing up card X".
Neither testing your configuration nor trying to back up has any detrimental effects on the system. They just won't do what you expect during this time.

Action:
Please make sure all engineers are aware of these changes.

Name: Peter Dodge