GENT
by Honeywell

Technical Bulletin	TB 10076

To: System Integrators, Novar Gent Services	Date: 24/11/2005
	Status: Active
	Type: Gent/SI

Product – Part affected:
Vigilon I/O card working with remote printer
Details:
A problem has been found that when remote printer is selected the closing of the outer door turns both the internal and remote printer off. This is only a problem with the new short I/O cards using versions 3.75 & 4.09 or bellow.
Action:
Upgrade the I/O cards to V3.76 or V4.10 or later and MCC to V3.92 or V4.32 or later

Name: Peter Dodge