GENT
by Honeywell

Technical Bulletin	TB 10087

To: Gent by Honeywell, System Integrators & SMS	Date: 30/5/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Vigilon Panels - Displays

Details:
It has been noticed during factory final test of Vigilon panels that the contrast setting of the LCD display, in some cases, is very light on initial power up. A change has been made to the display PCB that eliminates the problem in the future. However there may be a small number of panels that may not be clearly read on power up.

Action:
If you have any problems with resetting the contrast please contact technical support and they will assist in the contrast setting process.

Name: Simon Foulkes