GENT
by Honeywell

Technical Bulletin	TB 10096

To: Gent by Honeywell, System Integrators & SMS	Date: 1/11/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Back compatible S3 sounder (S2IP-SN-x3) with latest panel and comm tool software.

Details:
Backwards compatible sounders connected to loop software 4.32/3.91 or later, the commissioning tool (V1.20) will clear the minimum, maximum and increment volume bytes when it downloads data to the control panel. This is because it fails to correctly recognise the products as S3 sounders.

This will mean no sound output will occur when sounders are activated and no fault indication of this will be displayed at the panel

This will be fixed in the new commissioning tool V1.21 due out January 2007.

Action:
If you have any site that is fitted with back compatible sounders and latest loop software 4.32/3.91. Please contact technical support.

Name: Peter Dodge