GENT
by Honeywell

Technical Bulletin	TB 10097

To: Gent by Honeywell, System Integrators & SMS	Date: 9/11/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Start up problems – Vigilon with MCC Cards

Details:
During testing of the new Vigilon panel a potential problem has been spotted with the MCC card at start up. Initialising of the card may fail and the panel display will remain blank. The component values on the MCC card has been modified and will be introduced with the new panel in January.

Action:
If the panel starts up and fails to initialize the MCC card at first attempt, the card should be exchanged..

Name: Peter Dodge