GENT
by Honeywell

Technical Bulletin	TB 10100

To: Gent by Honeywell, System Integrators & SMS	Date: 10/11/06
	Status: Active
	Type: SI / SMS

Product – Part affected:
Minimum software for back compatible S3 and new S4-34800 MCP

Details:
If you install new devices on panel software that are not compatible with the devise you are likely to corrupt the devices.

Minimum software for back compatible S3 sounders.

BS: LCC v3.40
I/O v3.40
LPC v3.46
NW does not matter

EN: LCC v4.01
I/O v4.01
LPC v4.01
NW does not matter

Minimum software for new S4-34800 MCP.

BS: LCC v3.40
I/O v3.40
LPC v3.40
NW does not matter

EN: LCC v4.01
I/O v4.01
LPC v4.01
NW does not matter

Action:
Please check panel software before adding new devices and ensure they are above those stated above.

A full list of all products and minimum software are available on www.gentexpert.co.uk under the FAQ section “minimum software required to run”.

Name: Peter Dodge