GENT
by Honeywell

Technical Bulletin	TB 10115

To: Gent by Honeywell, System Integrators & SMS	Date: 24/10/07
	Status: Active
	Type: SI / SMS

Product – Part affected:
Vigilon panels printing Pre-fires and not working with Ascom pagers (short IO card only).

Details:
Short IO cards, printing all pre-fire events when the printer is on, or not working with Ascom pager system when using the Ascom setting on the IO card.

The latest released of IO cards "versions 3.77, 4.11" will no longer print pre-fire events as per the old long IO cards.
This release of IO card also fixes the issue where it would not talk to Ascom pager systems correctly when set to the ascom protocol.

Action:
Ensure all engineers are aware of these changes.

Name: Peter Dodge