GENT
by Honeywell

Technical Bulletin	TB 10121

To: Gent by Honeywell, System Integrators & SMS	Date: 15/7/08
	Status: Active
	Type: SI / SMS

Product – Part affected:
Vigilon and Compact - Class Change overrun.

Details:
It has been noticed on a number of sites that use the class change function that occasional sounders may not silence at the end of the input. This has now been fixed in loop software version 4.37.

Action:
Ensure all engineers are aware of the new software and its related fixes.

If you have a site suffering from the above issue please use express exchange to request a loop card upgrade, make reference to this TB.

Name: Peter Dodge