GENT
by Honeywell

Technical Bulletin	TB 10126

To: Gent by Honeywell, System Integrators & SMS	Date: 21/11/2008
	Status: Active
	Type: SI / SMS

Product – Part affected:
Vigilon repeat, New MRC – fires out of order

Details:
A problem has been found that when multiple fire are displayed on the new MRC (released April 2008) they are displayed in reveres order. I.E. 1st fire will appear in front of the most resent fire and new fire will appear in front of the first fire.
Information displayed on the panel is still correct.

Action:
This issue is currently being looked at. Please look out for future TB's

Name: Peter Dodge