GENT
by Honeywell

Technical Bulletin	TB 10168

To: Gent by Honeywell, System Integrators	Date: 22/11/10
	Status: Active
	Type: SI

Product – Part affected:
Nano, devices in State 15

Details:
It has been noticed that if a device on a Nano panel is put into State 15 (disabling the device), this does not bring up the disablement light or log this event in the active log. But does disable the devices.

Although this is not a standards issue, Gent normally show this action as they would a device disablement.

Action:
Ensure all engineering are aware of this.

We would recommend that configuration files where states have been used are checked. To ensure that people have not inadvertently put devices into state 15, when another state was intended.

This issue will be fixed in the next release of panel software.

Name: Peter Dodge