GENT
by Honeywell

Technical Bulletin	TB 10177

To: Gent by Honeywell, System Integrators	Date: 12/2/12
	Status: Active
	Type: SI

Product – Part affected:
Comm tool 1.27 general release, 1,27 Sp1 &1.28. Token words

Details:
The latest versions of comm. Tool (1.27 general release, 1,27 Sp1 &1.28) tokenises all words possible within a label, where as previous versions only did this one it reached 32 characters

This could be a problem on old software version that do not have all the new token words

This will only be an issue on site with software older then v3.70 / v4.10, release May 2002

Action:

On these sites, check to make sure labels are still correct after uploading.

This issue can be overcome by abbreviating the word therefore preventing tokenisation or by using comm. Tool v1.26.

We would recommend abbreviating the labels rather than using comm. tool 1.26 as this could give you issues on other sites with newer devices.

This issue is being looked at for the next release of comm. tool

Name: Peter Dodge