GENT
by Honeywell

Technical Bulletin

TB:10194 | May 2014



Product parts affected

Vigilon 4/6 loop and Vigilon Compact Main Control Software v4.52 Released

Details

This bulletin is a follow-up to TB10193 describing a potential life safety issue with networked systems using v4.51 of Vigilon Main Control Software.

Following comprehensive testing, v4.52 of Vigilon Main Control Software has been released to our factory. All Vigilon and Vigilon Compact panels shipped from our factory from 9th April 2014 onwards will contain v4.52 of Main Control Software. The issue identified in TB10193 has been eliminated in v4.52 of Main Control Software.

The issue described in TB10193:

Vigilon panels operating version 4.51 of main control software with network cause and effect linking more than one Master Sector may not operate as expected. As a result, in some circumstances, it is possible that the system may not sound an alarm or indicate a fire or fault condition.

Action:

No further action is required.

If you have any questions please contact Gent by Honeywell Technical Services on 0116 246 2134.

Gent By Honeywell
140 Waterside Road,
Hamilton Industrial Park,
Leicester, LE5 1TN.

t 0116 246 2000
f 0116 246 2300
e gentenquiry@honeywell.com
www.gent.co.uk