GENT
by Honeywell

Technical Bulletin

TB:10207 I November 2015

Product parts affected

MCC / MCB 4.53 and test mode.

Details

With the latest MCC / MCB, v4.53, when put into test mode.

Shortly after a test fire is reset the following message will appear on the screen for a short period of time.

"Task CC32 orphaned the CQ stage 0"

This is a message used during development and is normally inhibited in released software.

This message is not displayed during normal fire resets.

The message has no effect on the operation of test mode and is cleared down when the next message is displayed on the screen, normally a few seconds later.

Action

Ensure all engineers are aware of this message and that it has no effect on the operation of test mode.

This message will be inhibited in the next release off MCC / MBC software

For any further queries relating to this issue please contact Technical support on 01162462134 or email technical.services@honeywell.com