GENT
by Honeywell

Technical Bulletin

TB 10228 | November 2019


Product Parts affected

Gent Mains Interface (S4-34440-02 and/or S4-34440-12) Changes to PCB

Details

We have made changes to the Mains powered interface to support new intrinsically safe offering of peripherals and barriers.

Boards made from the start of October 2019 are now version 1.04. See below picture for chip location with version number



These alterations have changed the end of line used for sounder circuits and barrier for the intrinsically safe offering.

Action

Make sure all engineers are aware of this change.
If carrying out new install or replacing existing mains interface PCB's please review these changes as they may require other changes on site.
For more information on this please see the mains interface manual 4188-968 issue 8 on gent expert (downloads / manuals and datasheets / addressable loop devices / mains interface)