

Honeywell

Honeywell Analytics
Gas Detection

IntelliDoX BW Clip4
50127307-013

ERRATA CARD

New information for the IntelliDoX BW Clip4:

Ensuring proper operation of the IntelliDoX BW Clip4 module

After performing a bump test or calibration, remove the detector from the IntelliDoX docking module to allow any residual gas to clear. The detector will then begin a 90-second countdown. When this countdown is complete, the detector will return to normal operating mode. If necessary, it can then be returned to the IntelliDoX module.

Leaving the detector in the docking module may cause it to fail the calibration. If a detector is bump tested and then a calibration is performed without removing it from the docking module, residual gas may cause the calibration to fail.



Contacting Honeywell Analytics Gas Detection

Canada: 1-800-663-4164

USA: 1-888-749-8878

Europe: 00800 333 222 44

Other countries: +1-403-248-9226

Email: info@gasmonitors.com

Website: www.honeywellanalytics.com

Americas

405 Barclay Boulevard

Lincolnshire, Illinois

USA 60069

Europe

Javastrasse 2

8604 Hegnau

Switzerland