

PB22-012

June 24, 2022

Re: Wired High-Speed Network Modules Update

This product bulletin is in continuation to our communication on High-Speed Network Control Module product discontinuance dated October 5, 2020.

Notifier Pacific had set aside support stock of legacy High Speed NCM cards and we have exhausted all support stock of legacy wired HS-NCM cards. All orders for wired High-Speed NCM (for new sites) should be on the new High Speed NCM (-2) cards. The new High-Speed Network wired modules was launched in October 2020, and we are accepting orders for new parts.

The list of replacement wired HS-NCM parts is included below.

Old Item Code	Description	Status	New Replacement Part#
HS-NCM-W	Hi-Speed Network Control Module, TWISTED-PAIR Wire	Discontinued	HS-NCM-W-2
HS-NCM-WMF	Hi-Speed NCM, Wire / MF, Multi-mode optical fibre	Discontinued	HS-NCM-WMF-2
HS-NCM-WSF	Hi-Speed NCM, Wire / SF, Single mode optical fibre	Discontinued	HS-NCM-WSF-2

An HS-NCM product FAQs has been prepared that has all the information about transitioning to new cards. This FAQ document can be used as reference when talking to customer about the transition to new High Speed NCM.

For any technical questions pertaining to the new or current High-Speed Network wire modules please contact Technical Service:

Technical Support Fire Pacific (Toll Free):

Australia: 1800 220 345

New Zealand: 0800 220 345

Email: HBTPacificFireSupport@Honeywell.com