

VERIPRO[®] CALIBRATION CHECK

(Recommended Bi-annually)

Cost: \$130 USD

SERVICES INCLUDED

- Acoustic check of VeriPRO headphones and audio processor
- Check all components for proper connection
- Replace VeriPRO headphone ear cushions
- Replace any defective parts under warranty
- Refill sampler tube of Howard Leight[®] earplugs
- Provide calibration certificate
- Turnaround time for service after receipt by Honeywell is approximately 1 week
- Free return shipping once service is complete



SHIPPING INSTRUCTIONS

- Email hsrepairs@honeywell.com with your request and supply your company name, address, and phone number
 - An RMA will be sent to you via email
- Pack VeriPRO headphones, audio processor, USB cable and sampler tube in original carrying case
 - Enclose a copy of the RMA inside the box
- Pack in an appropriately sized box with protective material
 - Honeywell assumes no liability for damage on inbound shipping (by customer)
- Label the package with shipping address for San Diego that is on your RMA

WARRANTY SERVICE

- Honeywell will replace, at no charge, any defective parts due to defects in material and workmanship
- For damage due to misuse, abuse, alterations, or improper maintenance, Honeywell will notify customer of any parts needing replacement at an additional cost

PAYMENT METHODS

- Payment may be made by credit card. For security reasons, please call us with your credit card information once calibration services are completed.
- Distributors with account will be billed following delivery of services. If you have a distributor account, please provide p/o for \$130.00 when requesting RMA.

For more information

You can reach us at 800-873-5242, Option 5
for any questions or assistance.

Honeywell Industrial Safety

9680 Old Baires Rd
Fort Mill, SC 29707
1 (877) 841-2840
www.honeywell.com

VeriPRO Cal Check Sell Sheet | 08/21
© 2021 Honeywell International Inc.

Honeywell
HOWARD
LEIGHT