



Agency Model: SL-ES-G

Table with 8 columns and 4 rows, providing product documentation availability in various languages: English, Spanish, Portuguese, Chinese, Japanese, Korean, Arabic, and Hebrew.

FCC Part 15 Statement. This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: 1. This device may not cause harmful interference. 2. This device must accept any interference received, including interference that may cause undesired operation.

Table with 8 columns and 2 rows, providing caution and warning information in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Para su uso en México, la operación de este equipo está sujeta a las siguientes dos condiciones: 1. Es posible que este equipo o dispositivo no cause interferencia perjudicial. 2. Este equipo o dispositivo debe aceptar cualquier interferencia, incluyendo la que pueda causar su operación no deseada.

Canadian Compliance. This ISM device complies with Canadian RSS-210. Operation is subject to the following conditions: 1. This device may not cause harmful interference. 2. This device must accept any interference received, including interference that may cause undesired operation.

Table with 8 columns and 2 rows, providing technical specifications and performance data in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing technical specifications and performance data in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing CE marking information and compliance details in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing CE marking information and compliance details in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

United Kingdom Contact: United Kingdom Honeywell Scanning and Mobility, Honeywell House, Skimped Hill Lane, Bracknell, Berkshire, RG12 1EB Phone: +44 (0)1344921052

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

Table with 8 columns and 2 rows, providing safety warnings in multiple languages, including English, French, German, Italian, Spanish, Chinese, Japanese, Korean, Arabic, and Hebrew.

